


NO. 0362 **PRO Wear sweatshirt | contrast**



Description (measured in cm)	XS	S	M	L	XL	2XL	3XL	4XL	5XL	6XL
A: ½ Chest width	52	55	58	61	64	67	71	75	79	83
E: Front length from high point shoulder	68	70	72	74	76	78	80	82	84	86
H: Shoulder to shoulder	47	48.5	50	51.5	53	54.5	56.5	58.5	60.5	62.5
K: Sleeve length - long	62	63	64	65	66	67	68	69	70	71
L: ½ upper arm width	22	23	24	25	26	27	28.2	29.5	30.7	31.9

How to measure



Tolerance +/- in cm

A	E	H	K	K2	L
1.5	1.5	1.5	1.5	1	1

The measurements in a product measurement chart refer to measurements made directly on the clothing. Lay the garment out flat on an even surface without stretching it. Take the measurements as shown by the arrows and select the size that fits. Use a tape measure for the best results. The tolerances in the measurement chart are based on when the item is received from ID® and not